

JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

FILE COPY

September 21, 2006

Karren Martin, Administrator Golden Age Heritage Home - East P.O. Box 47 Preston, ID 83263

Dear Ms. Martin:

On September 7, 2006, a life safety code survey was conducted at Golden Age Heritage Home - East. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

FORM APPROVED Bureau of Facility Standards								
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - BUILDING 1 B. WING		COMPLE	(X3) DATE SURVEY COMPLETED	
		13/030	STREET AD	ADDRESS, CITY, STATE, ZIP CODE		09/07/2006		
NAME OF PROVIDER OR SUPPLIER GOLDEN AGE HERITAGE HOME - EAST			175 EAST 3RD NORTH PRESTON, ID 83263					
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTION CROSS-REFERENCED TO THE DEFICIENCY)	E ACTION SHOULD BE COMPLETE D TO THE APPROPRIATE DATE			
R 000	Initial Comments			R 000				
	compliance with the Rules for Residenti in Idaho. No core of the standard fire/life		of the Facilities ad during ucted on					

Bureau of Facility Standards

TITLE

(X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE